

Dear Customer

SAFETY NOTICE - Intergas HRE 40SB Component Upgrade

We understand that you have an Intergas HRE 40SB boiler installed in your property. We wish to inform you that during our stringent quality & safety checks it has come to our attention that some of the seals on this boiler model need to be replaced, this is to ensure that your boiler meets our quality and safety standards.

Please can you call the Service Department on: **01527 888000 & select option 2** so that we can arrange for an Intergas engineer to carry out the seal replacement.

Alternatively you can email: service@intergasheating.co.uk so we can get in contact with you.

It is important that you contact us, otherwise this could lead to a boiler breakdown which we wish to avoid.

Yours sincerely

Intergas Technical & Service Department

Intergas Heating Limited

Registered office:
Building 94,
Bay 1 Vantage Point,
The Pensnett Estate,
Kingswinford
DY6 7FS

T 01527 888000
F 01384 279480
E info@intergasheating.co.uk
I www.intergasheating.co.uk

ING Bank London
Sort Code **238859**
Account No. **20362431**
SWIFT/BIC **INGBGB22**
BAN **GB48INGB23885920362431**

VAT Reg. No. **928553006**
Company Number **6459477**